

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH

MEADOW LAKE, SK, S9X 1Z5

Customer

Name
Address
City
Postal Code
PhoneNumber
Email

Vehicle

VIN 2FMPK4J90JBC21655
Year 2018
Make FORD
Model EDGE
Engine TWIN-SCROLL 2.0L I4 ECOBOOST
Fuel
Stock Number N6637A
License/Stock
Date In 08/21/2020
Completed Date 09/18/2020
Odom 94964

Inspection

Service Order 103166
Advisor Andrew Spencer
Tech Clay Martin

Exterior of the vehicle

vehicle modifications Pass
Comments:
exterior lights operational Pass
Comments:
exterior damage Pass
Comments:
windshield: cracked, chipped or sandblasted Pass
Comments:

Measure and Inspect Tire Tread Depth and Condition

Pass: 6/32" or More
Caution: 4/32" - 5/32"

Fail: 3/32" or less

Left front tire tread depth Pass
Right front tire tread depth Pass
Left rear tire tread depth Pass
Right rear tire tread depth Pass
Inspect overall tire wear and condition
Comments:

Under The Hood

Engine: examine for leaks, damage and abnormal noises, oil condition and oil level Pass
Comments:
Air Inlet system: air filter, filter box and inlet tube are clean Pass
Comments:
Emission System: visually inspect to ensure all components are intact with no modifications Pass
Comments:
Radiator/Cooling System: no leak, damage or wear to the water pump, overflow bottle, hoses, fan, coolant is in good condition and full Pass
Comments:
Automatic Transmission: no leaks, or damage. Fluid is in good condition and correct level Pass
Comments:
Power Steering: pump, gear, and hoses have no leaks or damage Pass
Comments:
Electrical: cables are corrosion-free, starter and alternator are operational, and wiring harnesses are intact and without corrosion or modifications Pass
Comments:
Air Conditioning: compressor, clutch and hoses have no leaks, damage, or unusual noises Pass
Comments:
Brake System: no leaks or damage. Fluid is at proper level and clean Pass
Comments:

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH

MEADOW LAKE, SK, S9X 1Z5

Under the Vehicle

Transmission or Transfer Case: no leaks, damage or wear Pass

Comments:

Half Shaft and CV Joints or Drive Shaft and U-Joints: no leaks, damage, or wear Pass

Comments:

Brake System: no leaks, damage or wear Pass

Comments:

Steering System and Linkage: no leaks damage or wear Pass

Comments:

Suspension System: no leaks, damage, or wear Pass

Comments:

Axles: no leaks, damage or wear Pass

Comments:

Exhaust System: no leaks, damage. All components in place including convertors Pass

Comments:

Frame/Undercarriage: examine for damage or wear Pass

Comments:

Trailer Plug: harness intact, plug tested with trailer DR. Pass

Comments:

: No

Spare Tire, jack, and tools Pass

Comments:

Measure and Inspect Brake Lining and Condition

Pass: 6mm or greater (disc), 3mm and Greater (drum)

Caution: 4mm-5mm (disc), 2mm (drum)

Fail: 3mm or less (disc), 1mm (drum)

Measure front brake lining thickness Pass

Measure rear brake lining thickness Pass

Inspect brake system components Pass

Additional Recommendations

Additional Recommendations

Comments:

Vehicle Interior Checks & Road Test

Engine Performance: no problems (starting, poor performance, or smoking) Pass

Comments:

Transmission Performance: shifts smoothly with no unusable noise Pass

Comments:

Brake System: vehicle brakes without any issues (e.g. drift, pull, noise, vibration, etc). Parking brake functions properly Pass

Comments:

Steering: steering is tight and responsive with no unusual characteristics or noises Pass

Comments:

Suspension: vehicle exhibits no sign of harshness or loose suspension Pass

Comments:

A/C and Heater: operating properly with no unusual noises Pass

Comments:

Cruise Control: operating properly Pass

Comments:

Vibration/Noise: no unusual vibration or noise Pass

Comments:

Instrument Warning Lights - No warning lights illuminated while operating the vehicle Pass

Comments:

Wipers/Washer: no streaks or inconsistent spray Pass

Comments:

Instrument Guages: working correctly Pass

Comments:

Power Seats: operating correctly Pass

Comments:

Lights: functioning correctly Pass

Comments:

Horn: operates correctly Pass

Comments:

Windows/Locks: operating correctly Pass

Comments:

Mirrors- Operate correctly (power and manual) Pass

Comments:

Moonroof Pass

Comments:

Clock/Audio System Pass

Comments:

Other Switches/Controls Pass

Comments:

Heated Backglass Pass

Comments:

Power outlets work Pass

Comments: