

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH
MEADOW LAKE, SK, S9X 1Z5

Customer

Name PINERIDGE FORD SALES
Address
City MEADOW LAKE, SK
Postal Code S9X 1Z5
PhoneNumber (306) 236-1810(w)
Email

Inspection

Service Order 103837
Advisor Gerri Moeller
Tech Rick Arnold

Exterior of the vehicle

vehicle modifications Pass
Comments:
exterior lights operational Pass
Comments:
exterior damage Pass
Comments:
windshield: cracked, chipped or sandblasted Fail
Comments: CRACKED

Measure and Inspect Tire Tread Depth and Condition

Pass: 6/32" or More
Caution: 4/32" - 5/32"
Fail: 3/32" or less
Left front tire tread depth Pass
Right front tire tread depth Pass
Left rear tire tread depth Pass
Right rear tire tread depth Pass
Inspect overall tire wear and condition
Comments: 8/32

Vehicle

VIN 2C4RC1BG6FR584255
Year 2015
Make CHRYSLER
Model TOWN & COUNTRY
Engine 3.6L PENTASTAR VVT V6
Fuel
Stock Number N6671B
License/Stock
Date In 10/26/2020 1:52:35 PM
Completed Date 10/27/2020
Odom 70901

Under The Hood

Engine: examine for leaks, damage and abnormal noises, oil condition and oil level Pass
Comments:
Air Inlet system: air filter, filter boxc and inlet tube are clean Fail
Comments: AIR FILTER
Emission System: visually inspect to ensure all components are intact with no modifications Pass
Comments:
Radiator/Cooling System: no leak, damage or wear to the water pump, overflow bottle, hoses, fan, coolant is in good condition and full Pass
Comments:
Automatic Transmission: no leaks, or damage. Fluid is in good condition and correct level Pass
Comments:
Power Steering: pump, gear, and hoses have no leaks or damage Pass
Comments:
Electrical: cables are corrosion-free, starter and alternator are operational, and wiring harnesses are intact and without corrosion or modifications Pass
Comments:
Air Conditioning: compressor, clutch and hoses have no leaks, damage, or unusual noises Pass
Comments:
Brake System: no leaks or damage. Fluid is at proper level and clean Pass
Comments:

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH
MEADOW LAKE, SK, S9X 1Z5

Under the Vehicle

Transmission or Transfer Case: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Half Shaft and CV Joints or Drive Shaft and U-Joints: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Brake System: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Steering System and Linkage: no leaks damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Suspension System: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Axles: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Exhaust System: no leaks, damage. All components in place including convertors	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Frame/Undercarriage: examine for damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Trailer Plug: harness intact, plug tested with trailer DR.	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments: : No				
Spare Tire, jack, and tools	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				

Measure and Inspect Brake Lining and Condition

Pass: 6mm or greater (disc), 3mm and Greater (drum)				
Cauton: 4mm-5mm (disc), 2mm (drum)				
Fail: 3mm or less (disc), 1mm (drum)				
Measure front brake lining thickness	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Measure rear brake lining thickness	Fail	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Inspect brake system components	Fail	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Additional Recommendations

Additional Recommendations
Comments: FRONT 7MM REAR 3MM

Vehicle Interior Checks & Road Test

Engine Performance: no problems (starting, poor performance, or smoking)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Transmission Performance: shifts smoothly with no unusable noise	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Brake System: vehicle brakes without any issues (e.g. drift, pull, noise, vibration, etc). Parking brake functions properly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Steering: steering is tight and responsive with no unusual characteristics or noises	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Suspension: vehicle exhibits no sign of harshness or loose suspension	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
A/C and Heater: operating properly with no unusual noises	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Cruise Control: operating properly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Vibration/Noise: no unusual vibration or noise	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Instrument Warning Lights - No warning lights illuminated while operating the vehicle	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Wipers/Washer: no streaks or inconsistent spray	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Instrument Guages: working correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Power Seats: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Lights: functioning correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Horn: operates correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Windows/Locks: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Mirrors- Operate correctly (power and manual)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Moonroof	Not Applicable	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments:				
Clock/Audio System	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Other Switches/Controls	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Heated Backglass	Not Applicable	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments:				
Power outlets work	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				